

KEYED SHEET NOTES


- 1 L/18.6 VMG 10 SF ON S+W WALLS
- 2 L/19.4 WS ON CEILING
- 3 M/20.5 VMG 100 SF AC
- 4 M/21.7 VMG 1 SF

GENERAL NOTES

- 1 FOR LCD DESTRUCTIVE TESTING LOCATIONS, SEE LOCATION AND SAMPLE SUMMARY.
- 2 THE LOCATION OF VAV'S (TERMINAL UNITS) IS APPROXIMATE

LEGEND

- CURRENT WATER STAINED SURFACE
- CURRENT MOLD GROWTH
- HISTORIC MOLD GROWTH
- HISTORIC WATER LEAK/ STAINED CEILING TILE
- ACTIVE WATER LEAK
- CURRENT WATER ON FLOOR
- HISTORIC WATER ON FLOOR
- DESTRUCTIVE TESTING LOCATION (HISTORIC)
- ROOM NUMBER
- LCD INSP. LOCATION NO FINDINGS
- LCD INSP. LOCATION ACTIVE LEAK
- LCD INSP. LOCATION WATER STAIN
- LCD INSP. LOCATION OTHER NOTATION SEE WDA SUMM.
- LCD INSP. LOCATION WITH MULTIPLE FINDINGS "A", "B", OR "C" AS INDICATED



PRIME CONSULTANT



REVISIONS

NO.	DATE	NOTES
1	11/23/08	DRAFT
2	12/14/08	FIELD EDITS
3	12/17/08	FIELD EDITS

CLIENT
STATE OF CALIFORNIA
DEPARTMENT OF GENERAL SERVICES

PROJECT LOCATION
BOARD OF EQUALIZATION
450 N STREET
SACRAMENTO, CA. 95814

PROJECT
STATE OF CALIFORNIA, DGS
BOE ASSESSMENT

DESCRIPTION
WATER DAMAGE
SURVEY

LOCATION
6TH FLOOR

SHT NO. 7
SHT NAME A6